



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000969

DATE: 20-Jul-2019

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	806-0674-20+D		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	8100603EA		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG305AAK/883B		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG387AAK/883B		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG401DJ+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG417LDJ+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG442CJ+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG445CY+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG445CY+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1050U-005+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1085LZ-25B2+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1091LUA-040+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1100U-75+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1270AB-70#		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1270AB-70IND#		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1314+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1813R-15-U+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1982-035-01-F5+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS21Q354B+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS2430AB-002-E1+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS2704RQC+T10		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28E01P-W0R+1T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28E05X-047-B5+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28EL25Q+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28EL25Q+U		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS33X42+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	DS9106L-PK0+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS9106S-PK0+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS9106S-YL0+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DSK4X-S+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	ICL7621ACSA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1021BETX+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1026BEEE+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1062CEUB+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1082ACUE+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1085ACSA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1091BCEI+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1093BCEG+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1121EGK+D		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX11291ENX+CGQ		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX11291ENX+TCGQ		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1142AEAP+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX11607EWC+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX11607EWC+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX11801EWC+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1245ACAP+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1245BCAP+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1265ACEI+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1271AENG+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX138EPL+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX139CMH+D		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14540EEWP+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14550AEETB+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14560EWC+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14587EEWL+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14589EEWL+TG2B		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14592EEWE+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14638EZA+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14646EEWE+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14677EZA+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14709ENL+TCGZ		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX149BCPP+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX152CPP+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15566TGTG+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16005DTE+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16014TT+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16021PTEM+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16033LLB31+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083XR+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16092UK28BGA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16092UK28BGA+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX160CPN+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16131WTNN00+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16931ATLR/V+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17007BGTI+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17009GTL+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17009GTL+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17020ETJ+TCCM		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17042G+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17042G+U		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17058X003+T10		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17841GUE+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17841GUE/V+TCEN		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX182BCWI+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX190ACWG+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX19695ZEXF+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1988ETM+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX200EWP+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX2151BETJ+TWCL4		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX267ACWG+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX2769BC/D		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX314LCPE+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX31782ETL+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX31820SLMCR+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3243CAI+TG38		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3377EETD+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3460CSD+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3468CPA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX3646ETG+TC86		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX399CPE+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4023ESE+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4053CPE+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4210BEUA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4391CPA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX44281UANS+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4482ASA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4482ASA+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4506MJA		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4530CPP+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4546CEE+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4550CWI+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4552CPE+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4572CAI+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4578CWP+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4758EWX+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4787EXK+TC7Q		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4950CTO+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4950CTO+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5021EUA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5023SASA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5087AATE+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5087AATE+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX535ACPA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX539ACPA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5581AEUP+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5860DUXH+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5860PUXH+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6331LUR+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6331LUR+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6377UR27+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6377UR27+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6387LT23D3+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6391KA46+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6391KA46+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX6427MRUR+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX642AESA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6461XR27+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6711LEXS+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6794TPLD2+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6866UK23D1S+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6868UK23D1S+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6881ETE+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6888BETE+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6961ATH+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX704TEPA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX706SMJA		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX709SCUA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX734CPA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX7405CPA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX7409CPA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX754ESE+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77665AEWQ+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77665AEWQ+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77819EWB+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77819XEWB+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX804TCSA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX814KEPA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX819LEPA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8563EEE+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT15+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT15+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT16+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT18+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT82+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YEXT16+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8744ETJ+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8744ETJ+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8841ELT33+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8877EZK25+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8877EZK25+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX9290GTM/V+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9372EKA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9550EZK+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9652ASA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX97000EWA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX97000EWA+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX97002EWP+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX97002EWP+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724AEBC+G45		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724AEBC+TG45		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX973CPA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX982CPA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX983EPA+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9880AEWM+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9880AEWM+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9895AEWX+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9895AEWX+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9963AGCCQ+D		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAXQ622X-2613+		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MX7524AQ		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MXD1815UR31+T		18-Oct-2019	18-Jan-2021	Part can no longer be manufactured