

Product Obsolescence Notification

#10570532

Urgent Obsolescence with Replacement: 43061

To: All active customers

From: **Niki Taylor**, Associate Product Manager, KK®

niki.taylor@molex.com

cc:

Date October 22, 2012

Series / Product Family: 43061 series KK® housing in glow wire, UL 94V-0 compliant material

Part Numbers Affected: See attached list for obsolete parts and replacements

Product Description: 3.96mm (.156") pitch KK® housing in glow wire UL 94V-0

Product Image:

Replacements: Replacements on attached list. Glow wire, UL 94V-2 nylon equivalents

Last Order Entry Date: 12/1/2012

LAST SHIP DATE 1/5/2013

For further information please contact your local sales representative.

PCN Obsolesence special note:

Due to catastrophic tooling failure running glow wire compliant material, Molex must obsolete the glow wire options effective immediately. The replacement parts are made of UL94V-0 polyester and are drop in replacements. To the obsolete parts. PLEASE CONTACT YOUR SALES REPRESENTATIVE TO VERIFY LAST TIME BUY AVAILABILITY. **Due to the condition of the tool, not all LTB requests can be accommodated.**

If no last time buy orders are received by Molex within 180 days after issue date of the Obsolescence GCN, Molex reserves the right to terminate production at any time at its own discretion. MOQ and lead time will be negotiated at time of order placement and will be dependent upon material availability. Molex will make all efforts to meet customer order requirements. Orders placed after Obsolescence Notification and subsequently cancelled will be subject to a cancellation charge.

Molex Connector Corp

2222 Wellington Court Lisle, Il 60532 TEL: 630-969-4747 www.molex.com

Obsolete Glow Wire	Replace with
430613002	430613009
430613003	430613010
430613004	430613011
430613005	430613012
430613006	430613013
430613007	430613014
430613008	430613015
430613031	430610031
430613107	430613037
430613207	430613038
430613307	430613039