

PRODUCT CHANGE NOTIFICATION

Product Category COPPER CONNECTORS 20220426-1

Product Group ENTERPRISE CONNECTIVITY

ISSUE DATE: 2-May-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Panduit's Cat 6A UTP Couplers use an aluminum foil tape applied to the coupler housing to achieve industry leading alien crosstalk performance. Panduit is making a permanent change to the color of the foil tape on all Cat 6A UTP Couplers. The old foil tape was colored similar to the color of the housing. Due to global material shortages Panduit will be providing couplers, independent of housing color, with a silver colored foil tape. This change will take place in Panduit's manufacturing facilities in the next few months and will be a permanent change. This change does not affect fit, form, function, or coupler performance.

See images of the new silver foil tape to the right.

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*			

IMPACTED PART NUMBER(s)
CC6X88BL
CC6X88IG
CC6X88IW
CC6X88RD
CC6X88YL
CC6X88BU
CC6X88GR
CC6X88OR

