

## **Product Change Notification (PCN)**

PCN Number	510667	Date Issued	July 22, 2021
Reason for Change	Change Supplier		
Change Type Description	This letter is to inform y the supplier is making a this notice. There will b performance as a resul	a change affecting e no negative impa	the part(s) identified in
Reason for Short Notice	Special Request		
Assessment of Change	Test report/Specificatio	on Test Report	
Internal Molex Qualification Date	July 21, 2021		
Sample Availability Date (Changed Part)	July 21, 2021		
Planned Implementation Date	August 23, 2021		
Method of Identifying Change	Special marking on the	product or packag	jing
Before Change	After C	Change	
Supplier's material         Raw Material         Molex Product           Current         LCP UL94 V-0         52837 / 52901 / 500597 / 5           Alternative         LCP UL94 V-0         52837 / 52901 / 500597 / 5           • The severe winter storm that had widespread impacts across the United States Mexico, and parts of Canada from February 13 to 17, 2021 has caused a globe various grades of resin. This extraordinary event, in conjunction with an already market, has caused immediate and severe disruption in the industry.	00598 series     Molex ma properties       00598 series     followed t       00598 series     relevant p       s, Northern     relevant p       al shortage for     You can s       y constrained     change. H	terial scientists conducted compreheners of resins between the original supplie by Molex internal qualification testing w product specifications before delivery.	er and alternative supplier. This is being which shall ensure that finished products meet e the pictures from before and after of this
<ul> <li>Due to these supply constraints, Molex identified an internal shortage of resin s would create a challenge to fulfill all orders. Therefore, we identified an alternat</li> </ul>			

- for the product families listed above. After applying of this change. Molex products listed above will be manufactured by one of them - the current supplier's material or the alternative supplier's one by the resin material supply situation.
- We apologize for the inconvenience, but in view of the urgency of this matter, if there is no particular reply to the change notified by this PCN, it will be considered that the change have been approved and will be implemented with the above Planned implementation Date. Part number Impacted
- Part number Impacted. See the attached impacted parts list.

Identification: For the first6 months of the production start by the alternative material, we will add "M" at the end of Traceability number (see the picture right) of the label to identify products made from alternative materials. Carton label (sample image)

## molex

**Product Change Notification (PCN)** 

You may address any technical inquiries regarding this PCN by sending E-mail to pcn\_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:510667**" in the e-mail Subject line for faster response.

## RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com

PCN #	Molex Part #	
510667	529010274	
510667	529010374	
510667	529010474	
510667	529010674	
510667	529010874	