




Product Change Notification (PCN)

PCN Number	509929	Date Issued	April 26, 2021
Reason for Change	Capacity change or tool replacement		
Change Type Description	This letter is to inform you that another set of tooling is being added to meet the current and future demands of this product. There will be no changes in the fit, form or function from the additional tooling when compared to the current tooling.		
Reason for Short Notice	New Capacity		
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports will be available after below listed date		
Internal Molex Qualification Date	May 22, 2021		
Sample Availability Date (Changed Part)	May 22, 2021		
Planned Implementation Date	July 15, 2021		
Method of Identifying Change	Cavity identification		

RELEASED

Before Change

Milli Grid 79107 and 79109 Series



- Above Products for illustrative purpose only

After Change

Overview

- As a valued customer, we wanted to notify that:
 - Molex is developing additional housing mold and assembly fixtures to support the new quantity demand from customers.
 - Cavity ID Location shall refer to product drawing
- Product Impact
 - no impact to fit, form or function
- Part Number Impact
 - Refer to attached impacted part no list
- FAI report and samples available upon request



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:509929**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

PCN #	Molex Part #
509929	791077003
509929	791077004
509929	791077005
509929	791077006
509929	791077007
509929	791077008
509929	791077009
509929	791077015
509929	791077016
509929	791077019
509929	791077209
509929	791091001
509929	791091003
509929	791091004
509929	791091008
509929	791091010
509929	791091014
509929	791091016
509929	791091021
509929	791098402
509929	791098404

Part numbers affected:

79107-7001
79107-7002
79107-7003
79107-7007
79107-7009
79107-7011
79107-7014
79107-7021
79107-7024
79109-1002
79109-1004
79109-1009
79109-1011
79109-8410